



CERTIFICATE

Hereby we certify that we have inspected on August 21, 2023, at WEBER-HYDRAULIK GMBH in Losenstein, Austria their BATTERY TELESCOPIC RAM and supervised the tests conducted on the BATTERY TELESCOPIC RAM.

SCOPE

Rescue equipment

Brand name:

WEBER RESCUE SYSTEMS

Type:

RZT 2-1170 E-FORCE3

Article number:

1094686 70 MPa

CONCLUSION:

The conclusions of our inspection are the following:

- 1. All tests complied with the standards EN 13204, 2016 edition and NFPA 1936, 2020 edition.
- 2. None of the tests caused malfunction to the equipment.

Nominal working pressure:

- 3. All the results from the tests were in compliance with the standards EN 13204, 2016 edition and NFPA 1936, 2020 edition.
- 4. All measurements were conducted correctly and the values were verified.

CLASSIFICATION:

ACCORDING TO EN 13204, 2016 edition

Type	Classification	Cutting performance	
RZT 2-1170 E-FORCE3	TR189/360-99/270-20,9		
	1911		GC TOTAL

NFPA 1936, 2020 edition

Type	Classification	-
RZT 2-1170 E-FORCE3	-	

THE COMPANY IST NEITHER AN INSURER NOR A GUARANTOR AND DISCLAIMS ALL LIABILITY IN SUCH CAPACITY. THE ABOVE REFLECTS OUR FINDINGS AT TIME AND PLACE OF INSPECTION. THIS CERTIFICATE DOES NOT RELIEVE SELLERS/SUPPLIERS FROM THEIR CONTRACTUAL RESPONSIBILITIES NOR DOES IT PREJUDICE BUYER'S RIGHT OF CLAIMS TOWARD SELLERS/SUPPLIERS FOR COMPENSATION FOR ANY APPARENT AND OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURING THEREAFTER.

Place and date of issuance: Vienna, Austria, 25 August 2023

Inspector: Josef Resch

Teamleader: Bettina König

S.G.S. AUSTRIA

CONTROLL-CO. GES.M.B.H.AUSTRIA

(AUTHORIZED AGENT OF

SOCIETE GENERALE DE SURVEILLANCE SA)

Grünbergstrasse 15 A-1120 Wien t: +43 (1) 512 25 67-0 f:+43 (1) 512 25 67-9

Page 1 of 1

SGSPAPER 20539961

SGS Austria Controll-Co Ges.m.b.H



This document is issued, on the Client's behalf, by the Company under its General Conditions of Service printed overleaf. The Client's attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Clients instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents.